

U. S. Department of Agriculture

FOREST SERVICE

V45 X

Chipewau NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th Mer.

Sec. 30, 32, 50, 52 Corner common to Sections

30, 32, and 29

Corner consists of a Corner (not) in place



State condition new

Dimensions above ground 6424 x 20 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Elm Elm

Diameter 30 12

Bearing N34W N2055'E

Distance 607 561

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

(Signature)


(Date)

(Title)

1096

Metal Location Poster is on a tree \_\_\_\_\_ inches diameter, on the \_\_\_\_\_ side of \_\_\_\_\_ from which this Corner bears \_\_\_\_\_ chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 142N R. 27W S. 14 Mer.