

U. S. Department of Agriculture
FOREST SERVICE

~~CHIPPewa~~ NATIONAL FOREST

V-9-10

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th Mer.
Meader - Corner common to Sections
20, and 23



Corner consists of a Brass Cap on Pipe in place
State condition good

Dimensions above ground 15" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes
If not, why? _____

Jerome P. Monahan
(Signature)
June 11, 1925
(Date)
J. P. [unclear]
(Title)

1050

Corner again.

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a

	Sec.	4	Sec.
	Sec.	1	Sec.

(Make sketch of topography near Corner)

T. 147N. R. 27W. S7E. Mer.