

U. S. Department of Agriculture

FOREST SERVICE

V-23-24

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. T-142 R. W Mer. 5211-

meander Corner common to Sections

25, and 30

Corner consists of a 1 P. (2) in place



State condition G.O.

Dimensions above ground 1" 23 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of meander is located meander

Pits are located meander

Sketch markings or Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 25	S 30		
BT	BT		

Species SP JP

Diameter 6" 6"

Bearing S 71 1/2 W S 51 1/2 W

Distance 96 102

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? meander

(Signature)

(Date)

(Title)

966

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 142N R. 27W STA - Mer.

U. S. Department of Agriculture  
FOREST SERVICE

123-24  
9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5<sup>th</sup> Mer.

M.C.

Corner common to Sections

25, and 36

Corner consists of a Iron pipe (not) in place



State condition J.E.

Dimensions above ground 1' - 38' inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species JP JP

Diameter 6 6

Bearing S 71° W S 51° W

Distance 96 102

Do you believe this to be a genuine Land Office Corner Yes

If not, why? \_\_\_\_\_

(Signature)

(Date)


(Title)

966

Corner again.

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. LAIN R. 270  
 5th Mer.

U. S. Department of Agriculture  
FOREST SERVICE

V-23,24

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142N R. 27W S. 12 Mer.

21. C

Corner common to Sections

25, and 36

Corner consists of a Iron pipe (not) in place

State condition J.E.

Dimensions above ground 1' - 08' inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

525			
536			

N W S E


NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

525	536		
BT	BT		

Species JP JP

Diameter 6 6

Bearing 571' W 551' W

Distance 96 102

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

(Signature)

(Date)

(Title)

966

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. H. N. R. 1700 5-17 Mer.