

U. S. Department of Agriculture
FOREST SERVICE

V-1

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 147 R. 28 S. 7th Mer.
Section Corner common to Sections

25, 26, 30, and 31

Corner consists of a Bross Cop on top of (not) in (place)
State condition good

Dimensions above ground 5" High inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>F147</u> <u>B28</u> <u>530</u>	<u>F147</u> <u>B29</u> <u>525</u>	<u>F147</u> <u>B29</u> <u>530</u>	<u>F147</u> <u>B28</u> <u>531</u>
<u>BT</u>	<u>BT</u>	<u>BT</u>	<u>BT</u>

Species SPRUCE ASPEN ASPEN SPRUCE
Diameter 4 8 9 7
Bearing N30°E N46°W S31°W S11°E
Distance 2 12 12.6 19.6

Do you believe this to be a genuine Land Office Corner?

If not, why?

(Signature)

(Date)

(Title)

112

U. S. DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

FIELD NOTES

CORNERS OF THE PUBLIC SURVEY

Corner again

Give any further facts which will aid in finding this


chains distant

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

V-1

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 147 R. 28 5th Mer.
SECTION Corner common to Sections
25, 26, 30, and 31

Corner consists of a BRASS CAP ON TOP OF (not) in place
State condition GOOD

Dimensions above ground 5" High inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T147 B28 530	T147 B29 525	T147 B29 530	T147 B28 531
BT	BT	BT	BT

Species SPRUCE ASPEN ASPEN SPRUCE

Diameter 6 8 9 7

Bearing N30°E N45°W S31°W S110°E

Distance 2 12 1206 196

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

(Signature)

(Date)

(Title)

112

Form 100 (Revised 1-25-34)

UNITED STATES FOREST SERVICE

STATION 2

CORNER OF THE METRIC SQUARE

Corner again.

Give any further facts which will aid in finding this


corner distant,

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

Form 874-0—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

V-1

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 28W 5th P. Mer.

Section

Corner common to Sections

25, 36, 30, and 31

Corner consists of a Brass cap on lead in place


State condition good

Dimensions above ground 8" high inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T147N
R28W
S30.BT

T147N
R29W
S25.BT

T147N
R29W
S36.BT

T147N
R28W
S31.BT

NE

NW

SW

SE

Species Spruce Aspen Aspen Spruce

Diameter 6.6" 8.8" 9.7" 7"

Bearing N30° E N45° W S31° W S11° E

Distance 2' 12' 12.6' 19.6'

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

W. Banks

(Signature)

10/10/34

(Date)


Tech. Foreman

(Title)

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant.

Give any further facts which will aid in finding this Corner again.

Corner located in Aspen pole type with a few spruce mixed in, surrounded by alder brush.



(Make sketch of topography near Corner)

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

V-1

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. ~~28~~ 28 29 5th Mer.

Section Corner common to Sections
 25, 30, 31, and 36

Corner consists of a Iron pipe (not) in place
 State condition with brass cap

Dimensions above ground _____ inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.
 CARDINAL POSITION DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T147N
 R29W
 S.36

T147N
 R29W
 S.25

T147N
 R28W
 S.30

T147N
 R28W
 S.31

BT

BT

BT

BT

Species Aspen Aspen Spruce Spruce

Diameter 10" 8" 8" 1" 6"

Bearing S33W N48W N25E S13E

Distance .20 .19 .03 .30

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Walterr Haberle

(Signature)

17/8/39

(Date)

Leader

(Title)

U. S. DEPARTMENT OF AGRICULTURE

FOREST SERVICE

CORNER OF THE PLATE

from which this Corner bears
 side of
 tree inches diameter, on the
 Metal Location Poster is on a
 chain distant,
 gives any further facts which will aid in finding this
 Corner again.

<p>Sec. 51</p>	<p>Sec. 52</p>	<p>Sec. 53</p>	<p>Sec. 54</p>
<p>Sec. 50</p>	<p>Sec. 51</p>	<p>Sec. 52</p>	<p>Sec. 53</p>

A-1

(State sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

✓

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 28 29W 5th Mer.

Section Corner common to Sections
25, 30, 31, and 36

Corner consists of a Iron pipe (not) in place
State condition with brass cap

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and
fill blanks below, giving bearings from Corner to Trees and
Distances in Links.

T147N R29W S36	T147N R29W S25	T147N R28W S30	T147N R28W S31
BT	BT	BT	BT

Species Aspen Aspen Spruce Spruce

Diameter 10" 8" 8" 6"

Bearing S33W N48W N25E S13E

Distance .20 .19 .03 .30

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Walter Haberle

(Signature)

17/8/39

(Date)

Leader

(Title)

Metal Location Poster is on a _____
 tree _____ inches diameter, on the
 side of _____
 from which this Corner bears
 _____ chains distant.
 Give any further facts which will aid in finding this
 Corner again.

<p>31</p>	<p>31</p>	<p>36</p>	<p>36</p>
<p>30</p>	<p>30</p>	<p>25</p>	<p>25</p>

(Make sketch of topography near Corner)