

Form 874-9—Revised May, 1918
U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

M117
Pasted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N R. 28 W 5 Mer.

S 1/16 Corner common to Sections
14 and 15

Corner consists of a 3" squared stake (not) in place
 State condition Fair

Dimensions above ground 36 inches.
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

		<u>1/16</u> <u>S</u>	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/16</u> <u>S</u>			
<u>BT</u>			

Species T.
 Diameter 4"
 Bearing S40W
 Distance 8 links

Do you believe this to be a genuine Land Office Corner? No.

If not, why? _____

Edward H. Henry

Signature.

Forest Ranger

Title.

12/12/28

Date.

T. 147 N. R. 2 & W. 5 Mer.

8-3027 (Make sketch of topography near Corner.)

Metal Location Poster is on a Spruce

tree 6 inches diameter, on the South

side of State

from which ~~the~~ Corner bears

80 chains distant.

Give any further facts which will aid in finding this

Corner again.

Well blazed line from

Sec. corner

to 14, 15, 22 and 23 bears

N 518 20 chains to the corner

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

M-17
Posted

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 147 N. R. 28 W. Mer.

S. 1/16 Corner common to Sections
14, and 15

Corner consists of a scribed stake (not) in place
State condition Fair

Dimensions above ground 2 1/2 ft. high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species ^{dead} B. Spr. _____

Diameter 3" _____

Bearing N. 70° W _____

Distance 7 ft. _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

W. Banks
(Signature)

9/18/34
(Date)

T. F.
(Title)

Faint, illegible text on ruled lines.

Located in 7c type

Corner again.

Give any further facts which will aid in finding this

10 ft chains distant.


from which this Corner bears *N 7° W*

side of

tree *1 1/2* inches diameter, on the

Metal Location Poster is on a *B. Spruce*

yellow



(Make sketch of topography near Corner)

T. 141N. R. 28W