

U. S. Department of Agriculture
FOREST SERVICE

J-25
Posted

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 147 N. R. 27 & 28 W. Mer.

Section Corner common to Sections

18, 7, 13, and 12Corner consists of a Squared stake (not) in placeState condition FairDimensions above ground 2 1/2 ft. high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species B. Sp. B. Sp.Diameter 5" 6"Bearing N. 37° E S. 70° WDistance 7 ft. 6Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

.....

.....

W. Banks
(Signature)


9/17/34
(Date)

T.F.
(Title)

located in a 76 type. The two
 block spruce~~s~~ considered as
 witness trees were never
 scribed but were blazed facing
 the corner and in such a
 manner as to indicate that
 they were intended as witness
 trees.

Corner again.

Metal Location Poster is on a
 tree inches diameter, on the
 side of
 from which this Corner bears
 chains distant.
 Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 121N. R. 27 & 28W

Mer.