

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N. R. 22 W. 5th. P. Mer.

Section Corner common to Sections  
29, 30, 31, and 32

Corner consists of a Wood Post (XXX in place)  
State condition Fair


Dimensions above ground 24 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig. B.T.			
B.T.			

Species Cedar Stb.

Diameter 12"

Bearing S. 11° W.

Distance 16

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

H. Heard

(Signature)

12/27/30  
(Date)

Compass Man  
(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears S. 28° W. 2.33'

side of

tree 8 inches diameter, on the S.W.

Metal Location Poster is on a sign



(Make sketch of topography near Corner)