

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N. R. 29 W. 5th P. Mer.

Section _____ Corner common to Sections

26, 27, 34, and 35

Corner consists of a Wood Post ~~mark~~ in place

State condition Good

Dimensions above ground 40 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>Orig. New B.T.</u>			
-----------------------	--	--	--

<u>B.T.</u>	<u>B.T.</u>		
-------------	-------------	--	--

Species Aspen Aspen

Diameter 6" 4"

Bearing S. 40° N. S. 65° E.

Distance 22 1/2 18 1/2

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? Re-established on old line

blazes South and West and 13.95 Chains

East of Orig. M.C.

John A. Gjelberg
(Signature)

8/23/19
(Date)

Jr. Civil Eng.
(Title)


Corner again.

Give any further facts which will aid in finding this
 chains distant.

From which this Corner bears **S. 87° E.**
 side of **Tree**

4 inches diameter, on the **East**

Metal Location Poster is on **S. 87° E.**



(Make sketch of topography near Corner)