

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N. R. 29 W. 5th. P. Mer.  
 Quarter Corner common to Sections

14, and 15

Corner consists of a Wood Post ~~cont~~ in place


State condition Fair

Dimensions above ground 24 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig. B. Ts.		
$\frac{1}{4}$	$\frac{1}{4}$	
S 14	S 15	

Species Down Tam'c. Tam'c.

Diameter 8" 6"

Bearing S. 83° E. N. 64° W.

Distance 7 22

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

H. Hoard

(Signature)


12/18/39

(Date)

Compass Man.

(Title)

Give any further facts which will aid in finding this  
 Corner again.  
 from which this Corner bears **S. 89° E. 0.198**  
 side of **Tree**  
 tree **5** inches diameter, on the **S. E.**  
 Metal Location Poster is on a **Cedar**



(Make sketch of topography near Corner)