

U. S. Department of Agriculture
FOREST SERVICE

Chippewa

Posted J 19

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *147* R. *29* S. *5* Mer.

Corner common to Sections

11, and *14*

Corner consists of a *Not found* (not) in place



State condition

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Dead Birch*

Diameter *10"*

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

Dave Prestidge
(Signature)

2-25-35
(Date)

Estimator
(Title)

J-19

*Station not found
 but marks of station
 are upon the same
 as found when
 last gone*

Corner again.

Give any further facts which will aid in finding this

chains distant.


from which this Corner bears

side of

bearing true

tree 10 inches diameter, on the

*side of
 Metal Location Poster is on a
 sink marks bearing
 on the West Coast*



(Make sketch of topography near Corner)

Mer. J-19

T 147 R 29