

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 29ⁿ 5th Mer.

Quarter Corner common to Sections
24, and 25

Corner consists of a iron pipe with (net) in place

State condition brass cap

Dimensions above ground 2"-12" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--



N. W. S. E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

 S/25	 S/24		
BT	BT		

Species Cedar W. Pine

Diameter 4" 18"

Bearing S25W N82W

Distance .10 .53

Do you believe this to be a genuine Land Office Corner? Y N


If not, why? _____

Walter Haberle
(Signature)

8/28/40
(Date)

Prof. Asst.
(Title)

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)