

U. S. Department of Agriculture
FOREST SERVICE

A-11

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N. R. 30 W. 5th. P. Mer.

Quarter Corner common to Sections

4, and 33 T. 148 N. R. 30 W.

Corner consists of a in center of road (not) in place


State condition

Dimensions above ground inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

County B.T.

$\frac{1}{4}$
S 33

B.T.

Species J. Pine

Diameter 12"

Bearing N. 18° E.

Distance 73

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

John A. Gjelhaug

(Signature)

10/27/39

(Date)

Jr. Civil Eng.

(Title)

Corner again.

Give any further facts which will aid in finding this


0.73 chains distant.

from which this Corner bears N. 11° E.

side of Tree

tree 18" inches diameter, on the N.E.

Metal Location Poster is on a N. Pine



(Make sketch of topography near Corner)

T 147 R. 50 W. 5th P. Mer.