

Form 874-0—Revised May, 1918  
**U. S. Department of Agriculture**  
**FOREST SERVICE**

C-13

Chippewa NATIONAL FOREST

**CORNERS OF THE PUBLIC SURVEY**

T. 147 N. R. 30 W. 5th. P. Mer.

Quarter Corner common to Sections

3, and 4

Corner consists of a Cedar Post (~~300~~ in place

State condition Good

Dimensions above ground 40 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

New B.T. $\frac{1}{4}$ S 4			
----------------------------------	--	--	--

B.T.			
------	--	--	--

Species Cedar

Diameter 4"

Bearing N. 70° W.

Distance 13

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? Found orig. scribed post in

place O.K.

John A. Gjelhaug

(Signature)


10/26/39

(Date)

Jr. Civil Eng.

(Title)

Give any further facts which will aid in finding this  
 Corner again.  
 chains distant  
 0.36  
 from which this Corner bears  
 S. 7° E.  
 side of Tree  
 tree 7 inches diameter, on the South  
 Metal Location Poster is on a Tan's.



(Make sketch of topography near Corner)

T. 147 N. R. 30 W. 5th. P. Mer.