

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

E-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY



T. 147 N. R. 30 W. 5th P. Mer.
Quarter Corner common to Sections

1, and 12
Corner consists of a Scribed Wood post in place
State condition Fair

Dimensions above ground 24 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Aspen
Diameter 4"
Bearing West
Distance 300


Do you believe this to be a genuine Land Office Corner? Yes
If not, why?

K.V. Styer
(Signature)

3/24/38
(Date)

Leader
(Title)

Metal Location Poster is on a
 Aspen tree 1 1/2 inches diameter, on the
 side of tree
 from which this Corner bears
 S. 76° W. 1.56
 chains distant.
 Give any further facts which will aid in finding this
 Corner again.



(Make sketch of topography near Corner)

T. 147 N. R. 30 W. 5th P. Mer.