

Corner again.

Give any further facts which will aid in finding this


0.38 chains distant.

from which this Corner bears

side of

tree 6 inches diameter, on the north

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 147 R. 31 S. 72 Mer. J-5

U. S. Department of Agriculture

FOREST SERVICE

P
57
36

55

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 31 5th Mer.

Section Corner common to Sections 7, 8, 17, and 18


Corner consists of a iron pipe (not) in place State condition Good

Dimensions above ground 2 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T147
R. 31
S-18



B9



Species Aspen Stump

Diameter 16"

Bearing S 80 W

Distance 10 ch

Do you believe this to be a genuine Land Office Corner? ?

If not, why?

Truaphy (Signature)

8/15/35 (Date)

(Title)

J-5