



U. S. Department of Agriculture  
FOREST SERVICE

J-13

513

Chippewa NATIONAL FOREST



CORNERS OF THE PUBLIC SURVEY

T. 147 N R. 31 W 5th P. Mer.

Section Corner common to Sections  
9, 10, 15, and 16

Corner consists of a Tam'c post (not) in place  
State condition Good

Dimensions above ground 48 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.




Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig. of Co. B.T.



Species Tam'c Stp.

Diameter 8"

Bearing S. 74° E

Distance 64

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

John A. Gjelhaug

(Signature)

Jr. Civil Engineer

(Title)

11-2-38

(Date)

J-13