

Corner again.

Give any further facts which will aid in finding this

1.89 chains distant.

from which this Corner bears 576 F

side of

tree 20 inches diameter, on the

Metal Location Poster is on a

	Sec.		Sec.
	Sec.	13	Sec.

(Make sketch of topography near Corner)

P-19

Met

576

31

R.

T. 147

U. S. Department of Agriculture

FOREST SERVICE

P-19

P
57
36
811

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 31 5th Mer.

Corner common to Sections

and 23

Corner consists of a *Iron nail* (not) in place

State condition *Good*

Dimensions above ground *6* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>c 1/4</i>	<i>c 1/4</i>		
<i>S-23</i>	<i>S-23</i>		
<i>BT</i>	<i>BT</i>		

Species *Aspen Oak*

Diameter *20" 16"*

Bearing *S76E N20W*

Distance *1.89ch 2.25ch*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

[Signature]
(Signature)

8/30/35
(Date)

(Title)