


This corner is located
 in section 23
 T47N R31E
 sec 23
 south of
 corner again.

Metal Location Poster is on a
 tree 8 inches diameter, on the north
 side of
 from which this Corner bears
 50
 chains distant.



U. S. Department of Agriculture
FOREST SERVICE

posted
N-19

N 19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *147* R. *31* Mer. *5*

14 Corner common to Sections
14, and *23*

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<i>14</i>			
<i>5</i>			
<i>14</i>			
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species *Ash* _____

Diameter *8* _____

Bearing *N-23°E* _____

Distance *50L* _____

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? _____

(Signature) _____

(Date) _____

(Title) _____

N-19