

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 147 N. R. 31 W. 5th P. Mer. Q-21

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

Q-21

Q-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N R. 31 W 5th P. Mer.  
South 1/16 Corner common to Sections

23, and 24  
Corner consists of a Brass cap on 1" Iron pipe ~~(not)~~ in place.  
State condition Good

Dimensions above ground 6 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 1/16 S. 24			
B.T.			

Species W. Oak  
Diameter 10"  
Bearing N. 80° E  
Distance 52

Do you believe this to be a genuine Land Office Corner? **Yes**

If not, why? \_\_\_\_\_

J. A. Gjelhaug  
(Signature)

Jr. Civil Engineer  
(Title)

7-11-38  
(Date)

Q-21