

U. S. Department of Agriculture
FOREST SERVICE

N-3

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 22 W 5 Mer.

1/4 Corner common to Sections
13, and 12

Corner consists of a post (act) in place

State condition 1/2 pipe
Good

Dimensions above ground 24 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<u>1/4</u>	<u>1/4</u>		
<u>5</u>	<u>5</u>		
<u>13</u>	<u>19</u>		
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/4</u>	<u>1/4</u>	<u>1/4</u>	
<u>5</u>	<u>5</u>	<u>5</u>	
	<u>18</u>	<u>18</u>	
	<u>BT</u>	<u>BT</u>	

Species 1 am dead, 1 am J Pine

Diameter 4" 5"

Bearing S14E N5E N29W

Distance 1.72 1.07 1.87

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

D. Poole
(Signature)

2-20-25
(Date)

ccc Enrollee
(Title)

Corner again.

Give any further facts which will aid in finding this


0.57 chains distant.

from which this Corner bears N 68 E

side of Tree

tree 3 inches diameter, on the NE

Metal Location Poster is on a *Tree (dead)*



(Make sketch of topography near Corner)

T. 19 N. R. 26 W. Mer. 5

Form 874-0—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

N-3

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 14th R. 25th Mer. 5

Corner common to Sections

18, and 19

Corner consists of a Post To Pipe (not) in place

State condition Good

Dimensions above ground 24 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	<u>SE</u>	<u>SE</u>	

Species Tim (Dead) Tim J Pine
 Diameter 4th 5th
 Bearing N44E N53E N24W
 Distance 1.72 1.97 1.87

Do you believe this to be a genuine Land Office Corner? Yes
 If not, why? _____

D. Poole

2-25-25

645 Parcel No

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant. **0.57**


from which this Corner bears **N68W**

side of

S70W

tree **3** inches diameter, on the **SE**

Metal Location Poster is on a **200 (200)**



(Make sketch of topography near Corner)