

U. S. Department of Agriculture  
FOREST SERVICE

L-7

Chippewa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 14 N R. 25 W 5<sup>th</sup> Mer.

C Corner common to Sections  
\_\_\_\_\_, \_\_\_\_\_, and 17

Corner consists of a Wood Stake (not) in place  
State condition Good

Dimensions above ground 30 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

			<u>1/4</u> <u>C</u>
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/4</u> <u>3</u> <u>17</u>			
<u>BT</u>			

Species Pine stump  
Diameter 16"  
Bearing S 95° E  
Distance 0.25

Do you believe this to be a genuine Land Office Corner? No

If not, why? Established by  
County engineers 1923

Ronald Parker  
(Signature)

2-1-35  
(Date)

C. C. Engle  
(Title)

Corner again.  
of old map of 1271  
W. of line center - 131 ft  
PNC 7-5-57

Give any further facts which will aid in finding this  
0.25 ft chains distant.  
from which this Corner bears N 88 W

side of Post  
inches diameter, on the W  
Metal Location Poster is on a Cedar Fence



(Make sketch of topography near Corner)

T. LEAN R. 25 W. 5th Mer.

U. S. Department of Agriculture  
FOREST SERVICE

L-7

*Chippewa* NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 25 W 5<sup>th</sup> Mer.

C Corner common to Sections  
....., and 17

Corner consists of a Wood Stake (not) in place  
State condition Good

Dimensions above ground 30 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

			<u>1/4</u> <u>C</u>
N	W	S	E

NW	SW	SE	NE

Mound of ..... is located .....

Pits are located .....

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/5</u> <u>17</u>			
<u>BT</u>			

Species Pine Stump

Diameter 16"

Bearing S 45 E

Distance 0.28

Do you believe this to be a genuine Land Office Corner? No

If not, why? Established by  
County engineer 1923

Ronald Poole  
(Signature)  
C. C. Cavalier  
(Title)

2-1-25  
(Date)

Corner again.

Give any further facts which will aid in finding this

0.25 chains distant.


from which this Corner bears N 84 W

side of

post 8 inches diameter, on the

Metal Location Poster is on a

*Corner from*



(Make sketch of topography near Corner)

T. 148 N. R. 25 W. 5th Mer.

U. S. Department of Agriculture  
FOREST SERVICE

L-7

Chippewa NATIONAL FOREST

## CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 25 W 5<sup>1/2</sup> Mer.5<sup>1/6</sup> Corner common to Sections  
-----, -----, and 17Corner consists of a 1<sup>1/2</sup>" Iron Pipe (not) in place

State condition Good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/16 #6

1/16 #6  
S 17

BT

Species NP NP

Diameter 5" 4"

Bearing N2-30W N70W

Distance 90L 1.9L

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? -----

Donald Poole

(Signature)

12-12-24





(Date)

(Title)

-----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----

N

Corner again.  
 Give any further facts which will aid in finding this  
 chains distant.  
 from which this Corner bears  
 side of  
 tree inches diameter, on the  
 Metal Location Poster is on a

	<p>Sec.</p>		<p>Sec.</p>
	<p>Sec.</p>		<p>Sec.</p>

(Make sketch of topography near Corner)