

Form 274-B—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

A15

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 25 W _____ 5 Mer.

_____ V4 Corner common to Sections
_____, _____, 3, and 34

Corner consists of a 3" aspen (not) in place
State condition good

Dimensions above ground 18" inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION			
S		S	
34		3	
N	W	S	E

DIAGONAL POSITION			
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 34	S 34		
B.T.	B.T.		

Species W. pine W. pine
Diameter 14" 18"
Bearing N 19 E Due N.
Distance 58 Li 85 Li

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Ervin Meagher

(Signature)

Field Ass't

(Title)

7-2-35

(Date)

1/4 COR IS ON S. W. side of open meadow
second growth ASPEN

Corner again.

Give any further facts which will aid in finding this


59 ft. chains distant.

from which this Corner bears S 87 E

side of tree

tree 5 inches diameter, on the S E

Metal Location Poster is on a W. Birch



(Make sketch of topography near Corner)

T. 148 N. R. 25 W. 5 Mer.