

Form 874-8—Revised May, 1918  
**U. S. Department of Agriculture**  
**FOREST SERVICE**

271  
*parted*

NATIONAL FOREST

**CORNERS OF THE PUBLIC SURVEY**

T. 14 R. 25 Mer. 5

Section Corner common to Sections  
35, 36, 1, and 2

Corner consists of a tree stub (not) in place  
 State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

\_\_\_\_\_ Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	5/8		
	BT		

Species \_\_\_\_\_ Birch \_\_\_\_\_

Diameter \_\_\_\_\_ 12 \_\_\_\_\_

Bearing \_\_\_\_\_ N 75° E \_\_\_\_\_

Distance \_\_\_\_\_ 10 \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? Not marked by the

(Signature),

(Date)

(Title)

Aug 1 33


Corner again.  
Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

side of *of 100 ft* inches diameter, on the

Metal Location Poster is on a *100 ft*



(Make sketch of topography near Corner)

T. 148 R. 25 Mer. 3