

U. S. Department of Agriculture

FOREST SERVICE

copy

~~0-21~~
0-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *148 N* R. *25 W* *52* Mer.

Corner common to Sections *14*, *22*, and *24*



Corner consists of a *stone* *4" Post* (not) a place State condition

Dimensions above ground *30* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Balsam Cedar*

Diameter *5"* *8"*

Bearing *S 89° W* *S 47° E*

Distance *32.5 Lks* *51.1 Lks*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? *Set by County Surveyor*

M. Urbeck
(Signature)

7/1/18
(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant. 13

from which this Corner bears S 13° E

side of *tree*

tree 4 inches diameter, on the *NE*

Metal Location Poster is on a *Boboam*



(Make sketch of topography near Corner)

T. 148 N. R. 25 W. 57 Mer.

U. S. Department of Agriculture

FOREST SERVICE

0-21
21

Shiipewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 25 W 5th Mer.

N 4/10 Corner common to Sections
23, and 24

Corner consists of a Yew tree (not) in place
State condition

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	14		
BT	BT		

Species Balsam Cedar

Diameter 5" 8"

Bearing S 24° W S 47° E

Distance 22.5 lks. 51.1 lks.

Do you believe this to be a genuine Land Office Corner? no

If not, why? set by County Surveyor


(Signature)

7/12/32
(Date)

(Title)

(Make sketch of topography near Corner)

T. 178N R. 13W S2 Mer.



Metal Location Poster is on a Balsam

tree 7 inches diameter, on the SE

side of Tree

from which this Corner bears

13 chains distant.

Give any further facts which will aid in finding this

Corner again.