

Camp
0071

U. S. Department of Agriculture
FOREST SERVICE

N-25



Chippewa NATIONAL FOREST ?
CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 25 W 5th Mer.

Section 13, 24 Corner common to Sections
60-27 59-27
23, and 4

Corner consists of a iron pipe - 4" Post (not) in place
State condition _____

Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 13 T 148 R 25

S 24 T 148 R 25

S 33 T 60 R 27

S 4 T 59-27

B.T

B.T

B.T

PT

Species	<u>cedar</u>	<u>cedar</u>	<u>Spruce</u>	<u>W. Pine</u>
Diameter	<u>5"</u>	<u>6"</u>	<u>4"</u>	<u>10"</u>
Bearing	<u>S 64° E</u>	<u>N 25° E</u>	<u>S 33° W</u>	<u>N 53° W</u>
Distance	<u>69.5 lks</u>	<u>95.4 lks</u>	<u>107.1 lks</u>	<u>204.0 lks</u>

Do you believe this to be a genuine Land Office Corner? NA

If not, why? _____

Notes taken from county notes

J. C. Murbach
(Signature)

1/12/37
(Date)

S. Clark
(Title) etc

Metal Location Poster is on a tree _____ inches diameter, on the side of _____ from which this Corner bears _____ chains distant. Give any further facts which will aid in finding this Corner again.

		Sec.	Sec.
		Sec.	Sec.

(Make sketch of topography near Corner)

T. R. Mer.

Supervisor
C.P.

U. S. Department of Agriculture
FOREST SERVICE

PP
NFS

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 14 & N R. 25 W 3rd Mer.

Section 13, 24, 33, and 4 Corner common to Sections
13, 24, 33, and 4 ^{T 60-27} ^{T 59-27}

Corner consists of a iron pipe - 4" dia. (not) in place
State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 13
T 148
R 25

S 24
T 148
R 25

S 33
T 60
R 27

S 4
T 59
R 27

B.T

B.T

B.T

B.T

Species cedar cedar Spruce W. Pine

Diameter 5" 6" 4" 10"

Bearing S 64° E N 25° E S 33° W N 53° W

Distance 69.8 lks 95.4 lks 107.1 lks 204.1 lks

Do you believe this to be a genuine Land Office Corner? No

If not, why? _____

Notes obtained from county Surveyor _____

J. C. Muebeck

(Signature)

7/12/37
(Date)

St. Clerk
(Title)

C.R.A.

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

Corner again.


Give any further facts which will aid in finding this chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)