

U. S. Department of Agriculture
FOREST SERVICE

L-25

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 148N R. 25-26W 5 Mer.

1/4 Corner common to Sections
13, and 18

Corner consists of a (not) in place



State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S
13

BT

Species N. Pine (Stump)

Diameter 14"

Bearing N. 72 E

Distance 0.48

Do you believe this to be a genuine Land Office Corner? Yes


If not, why?

Paul Nelson
(Signature)

1-18-25
(Date)

C.C.C. Enrollee
(Title)

Metal Location Poster is on a *Aspen* tree *6* inches diameter, on the *SE* side of *Tree* from which this Corner bears *S 30 E* *0.06* chains distant.
 Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 18N. R. 25-26W. S. Mer.