

U. S. Department of Agriculture
FOREST SERVICE

R 25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 26 W 5 th Mer.



Section Corner common to Sections
24 25 19, and 30

Corner consists of a Tam. stake (not) in place
State condition

Dimensions above ground 3" x 3" x 30" inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Tam (DEAD) Spruce (dead) Spruce (Live)

Diameter 7" 9" 10"

Bearing S 19° E N 35° E S 53° W

Distance 0.84 ch. 0.87 ch. 0.83 ch.

Do you believe this to be a genuine Land Office Corner?

If not, why? Questionable: bearing of corner stake. Bearing trees does not comply with original G.L.O. notes

Robert M. ...
(Signature)

Dec. 17, 1934
(Date)

Tech. Foreman
(Title)

Department of Agriculture

Corner again.

Give any further facts which will aid in finding this

chains distant


0° 83'

from which this Corner bears N 53° E

side of

tree 10" inches diameter, on the

Metal Location Poster is on a Spruce BT.



(Make sketch of topography near Corner)

R25

T. M. S. N. R. 25. 296 N. 5th Mer.