

Form 874-9—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

J5  
 D

Shingowa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148<sup>th</sup> R. 27<sup>th</sup> 5<sup>th</sup> Mer.

Section Corner common to Sections  
 7, 8, 18, and 17

Corner consists of a wooden post (not) in place  
 State condition placed by crew

Dimensions above ground \_\_\_\_\_ inches  
 Sketch grooves, letters, figures, or notches, on proper face or edge.  
 CARDINAL POSITION DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and  
 fill blanks below, giving bearings from Corner to Trees and  
 Distances in Links.

148 <sup>th</sup> 27 <sup>th</sup> 5 <sup>th</sup>	148 <sup>th</sup> 27 <sup>th</sup> ---	file	file
5-2			

Species Basswood 30 in. 1. Pine  
 Diameter 3.75 3.75 1.4  
 Bearing 153° 375° 176°  
 Distance 0.7 0.15 9.04 chains.

Do you believe this to be a genuine Land Office Corner? Yes.

If not, why? \_\_\_\_\_

*Jager*  
 (Signature)

8/30/35  
 (Date)

Forest Officer  
 (Title)

Faint, illegible text on a ruled background, possibly bleed-through from the reverse side of the page.

Corner again.

Give any further facts which will aid in finding this

0.24 chains distant.

from which this Corner bears


N 29 E

side of tree

tree 3 inches diameter, on the

Metal Location Poster is on a

BRIDGE



(Make sketch of topography near Corner)