

Form 874-B—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

E 15  
 P

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 27 W. 5 th Mer.

$\frac{1}{4}$  Corner common to Sections 3, and 10

Corner consists of a Tam. post (not) in place

State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

$\frac{1}{4}$		$\frac{1}{4}$	
S. 3		S. 10	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

$\frac{1}{4}$	$\frac{1}{4}$		
S. 10	S. 3		
B. T.	B. T.		

Species Tam. Tam.

Diameter Stump Snag

Bearing S. 32° W. N. 45° E.

Distance 0.20 0.06

Do you believe this to be a genuine Land Office Corner **YES**

If not, why? \_\_\_\_\_

Arthur H. Jager

(Signature)

Chief of Party, C.C.C.

(Title)

8/12/35.

(Date)

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

Corner again.

Give any further facts which will aid in finding this

0.02 chains distant.


from which this Corner bears Due South

side of

post

tree inches diameter, on the South

Metal Location Post is on a fence post



(Make sketch of topography near Corner)

T. 148 N. R. 27 W. S. 4th Mer.

Form 874-9—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

E-15


Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 27 W 5<sup>th</sup> Mer.  
 1/4 Corner common to Sections  
 3 & 10, and

Corner consists of a Iron Post (not) in place  
 State condition Good


Dimensions above ground 36" inches  
 Sketch grooves, letters, figures, or notches, on proper face or edge.



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Tree Tree  
 Diameter 5 1/2" 5 1/2"  
 Bearing S 30° W N 45° E  
 Distance 0.20 0.15

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

Arthur H. Jagan  
 (Signature)  
8/12/25  
 (Date)  
Compassman  
 (Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

D.O.R.

from which this Corner bears

Bve South

side of


Post

tree inches diameter, on the

South

Metal Location Poster is on a

fence post



(Make sketch of topography near Corner)

T. 148N R. 27W 5th Mer.