

U. S. Department of Agriculture

FOREST SERVICE

A17
S.O.P

Chippawa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 27 W. 5th Mer. Section

Corner common to Sections

3, and 2

Corner consists of a post (not) in place

State condition poor

Dimensions above ground 26 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

T148N	T148N
R27W	R27W
3.3	3.2
NW	SW
SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Harrison Adams

(Signature)

Chief of party, C.C.C.

(Title)

8/9/35.
(Date)

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
CORNER OF THE PUBLIC SURVEY

and South.
blazed line running east, west
Corner again.

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears S. 62° W.

side of
tree 8
inches diameter, on the Southeast
Metal Location Poster is on a Birch

