

U. S. Department of Agriculture
FOREST SERVICE

R21

Posted

Chippewa Acq. NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 27 W 5th Mer.

Section Corner common to Sections
23, 24, 26, and 25

Corner consists of a Birch post (not) in place
State condition Fair

Dimensions above ground 30 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION

T148N	T148N	T148N	T148N
R27W	R27W	R27W	R27W
S24	S23	S26	S25
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 25	S 26	S 23	
B.T.	B.T.	B.T.	

Species Oak Birch Birch
Diameter 7" stump 12"
Bearing S9° E. S39° W N52° W
Distance 57 li. 26 li. 57 links

Do you believe this to be a genuine Land Office Corner? **Yes**

If not, why? _____

Harrison Adams
(Signature)


2/13/35
(Date)

CCC Asst. Leader
(Title)

Dotted lines for writing notes.

Corner again.

Give any further facts which will aid in finding this
chains distant.
0.57
from which this Corner bears
S 52° E
side of section 23
tree 12 inches diameter, on the S E
Metal Location Poster is on a Birch



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

R-21

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N R. R7W 5th Mer.

Section Corner common to Sections 23, 24, 25, and 26

Corner consists of a Ash (not) in place



State condition New

Dimensions above ground 4 1/2 x 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

5-23

5-26

5-25

T-148N R-R7W 5-26

BT

BT

BT

BT

Species Birch J.P. Follen Oak J.Pine stub

Diameter 14" 16" 6" 5"

Bearing N-36°W S-46°W S-16°35'E S-20°W

Distance .44 1/2 .72 16 1/2 .37

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Balke

(Signature)

Leader

(Title)

4/29/37

(Date)

Corner again.

Give any further facts which will aid in finding this


~~corner distant.~~

from which this Corner bears *N. 36. W.*

side of *tree*

tree 1 1/4 inches diameter, on the *N.W.*

Metal Location Poster is on a *Block*



(Make sketch of topography near Corner)

T. 183 N. R. 22 W. Mer.