

Form 874-9—Revised May, 1918
 U. S. DEPARTMENT OF AGRICULTURE
 FOREST SERVICE

Posted
C-1

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *148 N* R. *28 W* Mer.

1/4 Corner common to Sections

6 and *14* ~ *28* and *1* and *14* ~ *29*

Corner consists of a *not found* (not) in place



State condition *~*

Dimensions above ground *~* inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S
6

BT

Species *Sp. v. l.*

Diameter *7"*

Bearing *~*

Distance *~*

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

Robert [Signature]


Signature.

Date.

Compass mark ~ 1928-29 Cruise

Title *C-1* 8-3027

(Make sketch of topography near corner.)



Metal Location Poster is on a Balsam

7 inches diameter, on the ~~near west~~ side of

cleared line

from which the ~~tree~~ bearing tree bears S 40° W (no declin)

1/2 chain distant.

Give any further facts which will aid in finding this

Corner again.

The bearing was N E of a

small N 5/8 line on the edge of

the line between a small stump of

oak on road and again a small

stump on road and a large stump

on road and a small stump on

road and a small stump on

W of stream fall