

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

P E 7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 28 W. 5 th Mer.

$\frac{1}{4}$ Corner common to Sections
 _____, _____, 5, and 8

Corner consists of a Spruce post ~~(set)~~ in place
 State condition Good

Dimensions above ground 3--48 inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

$\frac{1}{4}$ S. 5		$\frac{1}{4}$ S. 8	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

None found			

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Do you believe this to be a genuine Land Office Corner? **NO**
 If not, why? Too recent

W. C. ...

7/8/35.


(Date)

(Signature)
 Chief of party, C.C.C.

(Title)

Metal Location Poster is on a _____
 tree _____ inches diameter, on the _____
 side of _____
 from which this Corner bears _____
 chains distant.

Give any further facts which will aid in finding this
 Corner again.



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *148* R. *28* Mer. *6*



Corner common to Sections *111*, *5*, and *8*

Corner consists of a *Post* (not) in place
State condition *Sound side road*

Dimensions above ground *24* inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Oak*

Diameter *8*

Bearing *N43W*

Distance *144*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

*This corner offset from
cont. road.*

Floyd W. Johnson
(Signature)

Jan 24 1919
(Date)

Surveyor
(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant. *7 cent road*

43

from which this Corner bears

south


side of

7 inches diameter, on the

North

Metal Location Poster is on a

stone post



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

E-7

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 R. 28 S. 5th Mer.

Corner common to Sections 5, and 8

Corner consists of a Spruce post (not) in place

State condition Good

Dimensions above ground 3" x 48" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1/4 S5		1/4 S8	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner?

If not, why? _____


(Signature)

7/8/35 (Date)

(Title)

Lined writing area with horizontal dashed lines.

Corner again.
Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

E-7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146N R. 28W 5th Mer.

1/4 Corner common to Sections
5, and 8

Corner consists of a Spruce Post (not) in place



State condition 900

Dimensions above ground 2' x 4 8" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? NO

If not, why? too recent


(Signature)

(Date)

(Title)

28

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. W. B. N. R. 286 574 Mer.

U. S. Department of Agriculture
FOREST SERVICE

E-7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142N R. 28W 5th Mer.

1/4

Corner common to Sections

5, and 8

Corner consists of a Spruce Post (now) in place

State condition 9000

Dimensions above ground 2' x 4 1/2" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1/4		1/4	
55		58	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? **NO**

If not, why? **too Recent**

(Signature)

(Date)

(Title)

28

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 118N R. 28E 5th Mer.