

U. S. Department of Agriculture
FOREST SERVICE

x9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N R. 28W 5th Mer.

1/4

Corner common to Sections

32, and 33

Corner consists of a tan post (not) in place



State condition poor

Dimensions above ground 1" x 2" x 2" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION





N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species tan stub tan stub

Diameter 4" 4"

Bearing S62°W S89°E

Distance 63 43

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Walter Haberle

(Signature)

Leader

(Title)

8/23/38

(Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

side of tree

tree 3 inches diameter, on the


Metal Location Poster is on a

Spruce
Fast

N 80° W

87 K 5

Spruce 4" 57° E 237 K 5
Wt.



(Make sketch of topography near Corner)

Mer.

T. 148 N R. 28 W 5th

U. S. Department of Agriculture

FOREST SERVICE

X-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N R. 28W 5th Mer.

1/4

Corner common to Sections

32, and 33

Corner consists of a tan post (not) in place



State condition poor

Dimensions above ground 1'x2'x20" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species tan stub tan stub

Diameter 4" 4"

Bearing S62W S89E

Distance 63 43

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Walter Haberle

(Signature)

Leader


(Title)

5/23/38

(Date)

Corner again.
Spruce 4" 57° E 217 Ks
M.T.

Give any further facts which will aid in finding this
chains distant. 87 Ks
from which this Corner bears N 80° W
side of tree
3 inches diameter, on the East
Metal Location Poster is on a Spruce



(Make sketch of topography near Corner)

T. 148 N. R. 28 W. 574 Mer.

U. S. Department of Agriculture

FOREST SERVICE

X-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 28 W. Mer.

Corner common to Sections

52, and 53

Corner consists of a 20 post (not) in place


State condition

Dimensions above ground 112 2/3 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter 4 4

Bearing

Distance 15

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

(Signature)

8/25/55 (Date)

(Title)

1917
S. L. F.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree 3 inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. R. Mer.