

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

R 9
 7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N R. 28W 5th Mer.

Section—Corner common to Sections
20, 21, 28, and 29

Corner consists of a Tree (not) in place


State condition New

Dimensions above ground 30" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S-20			
BT			

Species Spruce

Diameter 3"

Bearing N. 46° W

Distance 123

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Boike

(Signature)

Chief of Party


(Title)

10/28/36
 (Date)

R-9 80

Corner again.
Corner is located in 76-type
and four 5-wp.

Metal Location Poster is on a
tree inches diameter, on the
side of
from which this Corner bears
chains distant.



(Make sketch of topography near Corner)

T. 148 N. R. 28 W. 5th-Mer.

R-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 122 n R. 28 5th Mer.



Corner common to Sections 20, 21, 28, and 29

Corner consists of a Tan. (not) in place
State condition new

Dimensions above ground 30" inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Spruce
Diameter 3"
Bearing N. 16° W
Distance 1.23

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

BALKE

10/28/36


(Signature) CHIEF OF PARTY

(Date)

(Title)

Corner again.
Corner located in T-6
the land on - 8 mwp

Metal Location Poster is on a
tree inches diameter, on the
side of
from which this Corner bears
chains distant.



(Make sketch of topography near Corner)

T. 148N R. 28W Mer. 525

R-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 n R. 28 W 5th Mer.

~~1~~ SEC

Corner common to Sections

20, 21, 28, and 29

Corner consists of a Tan. (see) in place

State condition REV.

Dimensions above ground 30" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S 20	S 29	S 28	S 21
---------	---------	---------	---------

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 20			
St			

Species Spruce

Diameter 3"

Bearing N.16^w

Distance 1.23

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

BALKE

(Signature)

10/28/36

(Date)

CHIEF OF PARTY

(Title)

80

148 N 28 W

Corner in forest in 76 -
Tupper Land, Sum. 8 1/2 acres

Corner again. N 9
Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 148 N R. 28 W Mer. 524