

U. S. Department of Agriculture

FOREST SERVICE

J 11  
f

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 R. 287 5th Mer.  
1/4

Corner common to Sections

9, and 16

Corner consists of a blazed by (not) in place

State condition good.

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4			
9			
B. T.			

Species Cedar

Diameter 14"

Bearing N 110° E

Distance .45 ch.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

*Herbert W. Moore*

(Signature)

Party Chief

7/19/35

(Date)


(Title)

J-11

Metal Location Poster is on a Cedar (B. P.) tree 14 inches diameter, on the SW side of *Tree* from which this Corner bears *S 1/2 W* 45 LKS chains distant.

Give any further facts which will aid in finding this Corner again.

Old trail leads by bearing tree.



(Make sketch of topography near Corner)

U. S. Department of Agriculture  
FOREST SERVICE

J-11

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146N R. 28W 5th Mer.

1/4 Corner common to Sections  
16, and 9

Corner consists of a (not) in place  
State condition new

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1/4 59			
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 59			
Bt			

Species cedar

Diameter 21"

Bearing N110E

Distance 45

Do you believe this to be a genuine Land Office Corner? yes

If not, why?


(Signature)

7/19/35

(Date)

(Title)

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 148 N R. 28 W 6th Mer.



-----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----

*577175*

Corner again.

Give any further facts which will aid in finding this

577175 chains distant.


From which this Corner bears

*S 100 W E*

side of *Tree*

tree 16 inches diameter, on the *SOUTH WEST*

Metal Location Poster is on a *GRAB*



(Make sketch of topography near Corner)

T. L. H. N. R. 28 W. 5TH Mer.

U. S. Department of Agriculture

FOREST SERVICE

5-11

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. \_\_\_\_\_ R. \_\_\_\_\_ Mer. \_\_\_\_\_

Corner common to Sections \_\_\_\_\_

Corner consists of a \_\_\_\_\_ (not) in place

State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_


(Signature)

(Date)

(Title)

UNITED STATES FOREST SERVICE  
COMMISSIONER OF THE FOREST SERVICE  
WASHINGTON, D. C.

Corner again.  
Give any further facts which will aid in finding this  
Metal Location Poster is on a  
tree 14 inches diameter, on the  
side of  
from which this Corner bears  
chains distant.



(Make sketch of topography near Corner)

T. L. M. R. 174  
Mer.