

U. S. Department of Agriculture

FOREST SERVICE

C-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 28 W. 5<sup>th</sup> Mer.

14 Corner common to Sections 4, and 3

Corner consists of a Balsam poplar (not) in place


State condition good

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species SP 2. SNA 9

Diameter 2.5"

Bearing N 21° E

Distance 50

Do you believe this to be a genuine Land Office Corner? yes

If not, why?

(Signature)

(Date)

(Title)

10

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

|  |        |        |      |
|--|--------|--------|------|
|  |        |        |      |
|  | Sec.   |        | Sec. |
|  |        |        |      |
|  | Sec. 3 | Sec. 4 |      |

(Make sketch of topography near Corner)

T. 148 N. R. 28 W. 5-TH Mer.

U. S. Department of Agriculture

FOREST SERVICE

C-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N R. 28W 5th Mer.

14 Corner common to Sections 4, and 3


Corner consists of a Post (not) in place  
State condition good

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species SP. S. H. 29  
Diameter 2.5"  
Bearing N 21° E  
Distance 50

Do you believe this to be a genuine Land Office Corner? Yes  
If not, why? \_\_\_\_\_


(Signature)

(Date)

(Title)

10

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. LASH R. P. & Co. 5th Mer.

U. S. Department of Agriculture

FOREST SERVICE

C-13

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 25 N. R. 10 E. Mer.

Corner common to Sections

1, 2, 3, and 4

Corner consists of a B.A.L. (not) in place


State condition

Dimensions above ground 2.25 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner?

If not, why?


(Signature)

(Date)

(Title)

Blank lined area for notes at the top of the page.

Corner again.  
Give any further facts which will aid in finding this  
150 ft chains distant.  
from which this Corner bears S 75° W  
side of  
tree 10 inches diameter, on the S. W.  
Metal Location Poster is on a S.P. & M. 8



(Make sketch of topography near Corner)

Form 874-9—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

C13  
 P

~~Chi-owa~~ NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148<sup>th</sup> R. 28<sup>th</sup> 5<sup>th</sup> Mer.

1/4 Corner common to Sections  
 4, and 3

Corner consists of a placed by survey (not) in place  
 State condition

Dimensions above ground \_\_\_\_\_ inches  
 Sketch grooves, letters, figures, or notches, on proper face or edge.  
 CARDINAL POSITION DIAGONAL POSITION

|   |   |   |   |
|---|---|---|---|
|   |   |   |   |
| N | W | S | E |

|    |    |    |    |
|----|----|----|----|
|    |    |    |    |
| NW | SW | SE | NE |

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and  
 fill blanks below, giving bearings from Corner to Trees and  
 Distances in Links.

|       |  |  |  |
|-------|--|--|--|
| 1/4   |  |  |  |
| 3     |  |  |  |
| B. T. |  |  |  |

Species Sp. 2008  
 Diameter 20"  
 Bearing 21 E  
 Distance .50 ch.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

*W. Emmert*

(Signature) Party Chief 200

7/18/35  
 (Date)

(Title) C-13

