

Form 874-B—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

E 15

Chimewa NATIONAL FOREST P

CORNERS OF THE PUBLIC SURVEY

T. 148th R. 28th 5th Mer.

1/4 Corner common to Sections
 _____, _____, 3, and 10

Corner consists of a Corner (not) in place


State condition placed by _____

Dimensions above ground 0.67. inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



B.T.

B.T.

Species sap sturno

Diameter 18" 22"

Bearing S 80° N 20°

Distance .68 .80 ch.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

W. E. Emmert
 (Signature)

Party Chief, GND


(Title)

7/17/35

(Date)

E-15

Corner again.
Give any further facts which will aid in finding this
chains distant.
*26
From which this Corner bears
side of the
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

E-15

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 28 W. 5-72 Mer.

1/4 Corner common to Sections 3, and 10

Corner consists of a _____ (not) in place


State condition good

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Aspen Spruce
 Diameter 18 22
 Bearing S 80° W N 20° E
 Distance 68 80

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

(Signature)

(Date)

(Title)

18

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 148N R. 28W 5-H Mer.

U. S. Department of Agriculture
FOREST SERVICE

E-15

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 27 W Mer.

Corner common to Sections

14, 5, 10, and

Corner consists of a Put Case (not) in place


State condition

Dimensions above ground _____ inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/4 S</u> <u>10</u>			
<u>BT</u>	<u>BT</u>		

Species ASD Spore Slump

Diameter 18 22

Bearing SSW NRE

Distance 168 80

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

(Signature)

(Date)

(Title)

18

Corner again.

Give any further facts which will aid in finding this

36 links chains distant.


from which this Corner bears

M 61 S

side of *Tree*

tree inches diameter, on the *N. Side*

Metal Location Poster is on a *fallen apple*



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

E-15

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 N. R. 28 W. 5-74 Mer.

1/4 Corner common to Sections
3, and 10

Corner consists of a _____ (not) in place

State condition good

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 5/10			
B.T.	B.T.		

Species Aspen Spruce

Diameter 18 22

Bearing S86W N200E

Distance 68 80

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

(Signature)


(Date)

(Title)

18

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 1484 R. 280 5th Mer.