

U. S. Department of Agriculture

FOREST SERVICE

C-15

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 118 N R. 30 W Mer.

Corner common to Sections C 1/4 Sec 3, and

Corner consists of a SPR (not) in place



State condition good com

Dimensions above ground 24" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 4	C 4 S	C 4 S	
B+	B+	B+	

Species SPR SPV TAM SAK

Diameter 4" 12" 12"

Bearing N22°W 531°E N79°W

Distance 125 133 38

Do you believe this to be a genuine Land Office Corner? No

If not, why? Made Too

Recently

7/18/35 (Date)

(Signature) W E Emmert (Title)

142 #4

Blank lined area for notes.

Corner again.


Give any further facts which will aid in finding this

From which this Corner bears *03CH* chains distant.

side of *NORTH*

tree inches diameter, on the *N. Side*

Metal Location Poster is on a *Fence Post*



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

C15  
P

44121072

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 R. 28 5th Mer.

Center 1/4 Corner common to Sections 5, , and

Corner consists of a Spr. (not) in place

State condition Good.

Dimensions above ground 24 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

0 1 33	0 1 33	0 1 33	0 1 33
--------------	--------------	--------------	--------------

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S	0 1 S	0 1 S	
B. T.	B. T.	B. T.	

Species Spr. Spr. Tamarack snag

Diameter 14" 12" 12"

Bearing 122° W 331° E 172°

Distance .25 .33 .34

Do you believe this to be a genuine Land Office Corner?  10

If not, why? Placed too recently.

*W. J. Bennett*

(Signature)

Party Chief

(Title)

7/18/35

(Date)

C-15

.....

.....

.....

.....

.....

.....

.....


.....

.....

.....

Corner again.

Give any further facts which will aid in finding this  
 chains distant.  
 from which this Corner bears  
 side of  
 tree inches diameter, on the  
 Metal Location Poster is on a



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

C-15

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N R. 28W 5th Mer.

Center 1/4 Corner common to Sections  
....., and 3

Corner consists of a Spruce post (not) in place



State condition good post

Dimensions above ground 24 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of ..... is located .....

Pits are located .....

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Spr Spr Tan Spr

Diameter 14" 12" 12"

Bearing N72W S31E N72W

Distance 125 133 138

Do you believe this to be a genuine Land Office Corner? No

If not, why? Too Recent

(Signature)

(Date)

(Title)

140

Metal Location Poster is on a \_\_\_\_\_  
 tree \_\_\_\_\_ inches diameter, on the \_\_\_\_\_  
 side of \_\_\_\_\_  
 from which this Corner bears \_\_\_\_\_  
 chains distant. \_\_\_\_\_  
 Give any further facts which will aid in finding this  
 Corner again.

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

T. J. M. A. R. 280 Mer. 5 1/2

U. S. Department of Agriculture  
FOREST SERVICE

C-15

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N R. 28W 5th Mer.

Center 1/4 Corner common to Sections  
....., and 3

Corner consists of a Spruce Post (not) in place


State condition good post

Dimensions above ground 24" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E





NW SW SE NE

Mound of ..... is located .....

Pits are located .....

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Spruce Spruce Fir-Spruce

Diameter 1 1/4" 1 1/2" 1 1/2"

Bearing N22W S31E N72W

Distance 1.25 1.33 1.38

Do you believe this to be a genuine Land Office Corner? No

If not, why? Too Recent

(Signature)

(Date)

(Title)

140

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

	Sec.		Geo.
	Sec.		Geo.

(Make sketch of topography near Corner)

T. 1/16 N. R. 29 W. Mer. 5th