

N 17

U. S. Department of Agriculture

FOREST SERVICE

Posted

Chippewa Acq. NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 28 W. 5th Mer.

Section Corner common to Sections

14, 15, 22, and 23

Corner consists of a post (not) in place

State condition Good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

T148	T148	T148	T148
R28W	R-28W	R28W	R-28W
S15	S22	S23	S14
NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

R-28W			
S-15			
B. T.			

Species Birch

Diameter 14"

Bearing N. 62° W

Distance 19 links

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

H. Adams


(Signature)

1/16/35 (Date)

Asst. Leader (Title)

N-17

Metal Location Poster is on a None tree inches diameter, on the side of from which this Corner bears chains distant.
 Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

Form 874-9--Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

N-17

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 746 N R. 28 W 5th Mer.

Section 10 N Corner common to Sections
15, 14, 12, and 13

Corner consists of a post (not) in place
State condition good

Dimensions above ground 30" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1			
---	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

B28 515			
B7			

Species Birch

Diameter 14"

Bearing N62°W

Distance 19

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? _____

1/16/35

(Date)

(Signature)

(Title)

60

WATER RESOURCES DIVISION

FIELD NOTES

DATE: _____

LOCATION: _____

SECTION: _____

TIME: _____

WEATHER: _____

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

Mer.

5-74

T. L. H. & N. R. P. & W.

U. S. Department of Agriculture
FOREST SERVICE

N-17

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 746 N R. 28 W 5th Mer.
Section 11 Corner common to Sections
10, 14, 22, and 23

Corner consists of a post (not) in place
State condition good

Dimensions above ground 30" inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION

1			
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

BBB 515			
BT			

Species Birch
Diameter 14"
Bearing N62°W
Distance 19

Do you believe this to be a genuine Land Office Corner? yes
If not, why? _____

1/16/55
(Date)

(Signature)

(Title)

60

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 148 N. R. 28 W. 5th Mer.

U. S. Department of Agriculture
FOREST SERVICE

N-17

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 48 N. R. 28 W. 5th Mer.


Corner common to Sections
14, 20, and 27

Corner consists of a Post (not) in place
State condition Good

Dimensions above ground 3.0 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Aspen

Diameter 14

Bearing N 20° E

Distance 27

Do you believe this to be a genuine Land Office Corner? Yes


If not, why? _____

Maunika B. ...
(Signature)

1-12-35
(Date)

(Title)

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)