

Form 874-0—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

V19

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 28 W 5th Mer.

1/4 Corner common to Sections
26, and 35

Corner consists of a oak post (not) in place
State condition Fair

Dimensions above ground 3" X 3" X 20" inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION

<u>1/4</u>		<u>1/4</u>	
<u>5</u>		<u>5</u>	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>T148 N</u>			
<u>R28 W</u>			
<u>S 26</u>			
<u>0.1</u>			

Species Birch
Diameter 8"
Bearing N44° 30' W
Distance 1.01

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Walter Haberle

(Signature)

9/7/38
(Date)

Leader
(Title)

Off in line W.T.
Corner again.

Give any further facts which will aid in finding this


257K5 chains distant.

From which this Corner bears *N75°30' W*

side of *CORNER*

tree *8* inches diameter, on the *WEST*

Aspen Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 148 N. R. 28 W. 5th Mer.

U. S. Department of Agriculture

FOREST SERVICE

V-19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 R. 28 5th Mer.

14 Corner common to Sections

26, and 55

Corner consists of a Oak (not) in place


State condition Fair

Dimensions above ground 3" 3" 20" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Birch

Diameter 8

Bearing N 49° 30' W

Distance 1.01

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Walter A. Huber

(Signature)

Leader

(Title)

9/7/38


(Date)

Corner again.
Birch & N44°30' W 181 ft
C.O.F.

Give any further facts which will aid in finding this
25 lbs. chains distant.

from which this Corner bears
N25°36' W
side of 790

tree 8 inches diameter, on the East
Metal Location Poster is on a ASPEN



(Make sketch of topography near Corner)

T. 119 R. 28
Mer. 5th

Form 874-0—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

V-19



Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 148N R. 28W 5th Mer.

Corner common to Sections
26, and 35

Corner consists of a oak post (not) in place
Fair
State condition


Dimensions above ground 3" x 3" x 20" inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Birch

Diameter 8

Bearing N44°30'W

Distance 1.01

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Walter A. Habala

(Signature)

Leader

(Title)

9/7/38
(Date)

B. F. ...

Corner again

Give any further facts which will aid in finding this

chain distant.

257KS


from which this Corner bears *N75° 30' W*

side of *Corner*

tree *5* inches diameter, on the *West*

Metal Location Poster is on a

As per



(Make sketch of topography near Corner)