

U. S. Department of Agriculture
FOREST SERVICE

2-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 R. 28 S. Mer.

Corner common to Sections
35, 36, 2, and 1

Corner consists of a Spr. (not) in place



State condition good

Dimensions above ground 48 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species ASP Ash

Diameter 2 1/2" 1 1/2"

Bearing S 38° E S 27° W

Distance 58 96

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____


(Signature)

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this
chains distant.
From which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)

T. J. & A. R. 2800 5th Mer.