

Form 874-0—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

L21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N R. 28W 5th Mer.
Quarter Corner common to Sections

14, and 13

Corner consists of a Post (not) in place


State condition Placed by crew

Dimensions above ground 30" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Elm

Diameter 14"

Bearing S 20° W

Distance .67 chains

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Harrison Adams
(Signature)

4/15/35
(Date)


CCC Ast. Leader
(Title)

L-21

Blank lined area for notes at the top of the page.

Corner again
Fence run each way from corner.
Corner is placed by a bridge
on North side of road.
Give any further facts which will aid in finding this
0°40' chains distant.

from which this Corner bears N 20°E
side of tree
tree 14 inches diameter, on the North
Metal Location Poster is on a 15m



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

L-24

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 148N R. 28W 5TH Mer.

1/4 quarter Corner common to Sections
14, 13, and

Corner consists of a post (not) in place

State condition placed by CROW

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

GROWN OVER			

Species ELM

Diameter 14"

Bearing S 20° W

Distance 10 links 67

Do you believe this to be a genuine Land Office Corner? ~~Yes~~

If not, why?

Harrison Adams
(Signature)

4/15/35
(Date)


COC. DIST. LEADER
(Title)

Corner again.
Fences run each way
from the corner
corner is placed by a
bridge on north side of
road.

Give any further facts which will aid in finding this
No links chains distant.

from which this Corner bears N 20° E
side of tree

tree 14 inches diameter, on the north
Metal Location Poster is on a E-L-M



(Map sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

L-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N R. 28W 5th Mer.

1/4 Corner common to Sections

14, and 13

Corner consists of a post (not) in place

State condition new

Dimensions above ground 30" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

970W N 070			

Species Elm

Diameter 14

Bearing S 20° W

Distance 67

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

(Signature)


9/15/35

(Date)

(Title)

COMMITTEE ON THE SCIENCE OF THE
... ..
... ..
... ..
... ..
... ..

Corner again.
Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

L-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 28 W. 5th Mer.

14 Corner common to Sections
14, and 13

Corner consists of a post (not) in place
State condition new

Dimensions above ground 30" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

970 W over			

Species Elm

Diameter 14

Bearing S 20° W

Distance 67

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

(Signature)

9/15/36


(Date)

(Title)

58

Corner again.

Give any further facts which will aid in finding this
chain distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)

T. L. H. N. R. 200
5 + 5 Mer.