

Form 874-B—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

P
 C 25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 28W 5th Mer.

$\frac{1}{4}$ Corner common to Sections
 one, and six

Corner consists of a Balsam post (not) in place
 State condition placed by crew

Dimensions above ground 30" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

$\frac{1}{4}$ S 1.			
B T			

Species Spruce

Diameter 8"

Bearing S. 52° W.

Distance 0.07

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Arthur H. Jager

A. H. Jager

(Signature)

Chief of party.

(Title)

7/26/35

(Date)

C-25

Corner again.

Give any further facts which will aid in finding this


0.03 chains distant.

from which this Corner bears S 44° W

side of tree

tree 6 inches diameter, on the West

Metal Location Poster is on a Birch



(Make sketch of topography near Corner)

T. 13 N. R. 28 W. S. 4th Mer.

U. S. Department of Agriculture
FOREST SERVICE

C-25

Shippeno NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 14S R. 35W 5 Mer.

14 Corner common to Sections
1 & 6, and

Corner consists of a Balsam Post (set) in place



State condition Good (Placed by Crow)

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species SPRUC

Diameter 8"

Bearing S 52° W

Distance 7 Links

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

D. J. [Signature]

Chief of Party

7/26/35
(Date)

(Title)

Blank lined area for notes at the top of the page.

Corner again.

Give any further facts which will aid in finding this

corner distant.

3 LINKS

from which this Corner bears

S 111° W

side of


Tree

tree 6 inches diameter, on the

WEST

Metal Location Poster is on a

BIRCH



(Make sketch of topography near Corner)

T. 142 N R. 22 W S 7 Mer.

U. S. Department of Agriculture

FOREST SERVICE

C-25 R

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N R. 28W 5th Mer.

1/4 Corner common to Sections

Corner consists of a Batson post (not) in place


State condition Good

Dimensions above ground 30 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Spruce

Diameter 8"

Bearing S52°W

Distance 7

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

(Signature)

(Title)

7/24/35 (Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

S 44° 0' W

side of


tree

tree 6 inches diameter, on the

West

Metal Location Poster is on a

Birch



(Make sketch of topography near Corner)

T. HEN R. ESW 5-71 Mer.