

U. S. Department of Agriculture

FOREST SERVICE

XI

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 29 W. 5th. P. Mer.

Quarter Corner common to Sections  
31, and 36 T. 148 N.  
R. 30 W.

Corner consists of a Maple Post in place



State condition Good

Dimensions above ground 40 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig. B.Ts.

--	--	--	--

B.T.			
------	--	--	--

Species W. Pine W. Pine Stp. Rotten

Diameter 18" 22"

Bearing S. 6° E. N. 20° W.

Distance 22 32

Do you believe this to be a genuine Land Office Corner Yes

If not, why?

John A. Gjelhaug

(Signature)

11/14/39

(Date)

Jr. Civil Eng.

(Title)

Faint, illegible text on a ruled background, possibly bleed-through from the reverse side of the page.

Corner again.

Give any further facts which will aid in finding this


0.21 chains distant.

from which this Corner bears N. 6° W.

side of Tree

tree 18 inches diameter, on the N.W.

Metal Location Poster is on a W. Pine



(Make sketch of topography near Corner)

T 148 N. R. 29 W. 5th. P. Mer.