

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

V-1

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N. R. 29W. 5th P. Mer.

Section

Corner common to Sections

30, 31, and 25-36 <sup>T148N</sup> <sub>R30W</sub>

Corner consists of a Aspen Post (not) in place


State condition Good

Dimensions above ground 40 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION







Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig. B.T.

New B.T.



Species ETM Aspen

Diameter 12" 8"

Bearing N89W. N. 23E

Distance 91 19

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

John A. Gjelhaug

(Signature)

Jr. Civil Eng.

(Title)

11/20/39

(Date)

V-1

-----

-----

-----

-----

-----

-----

-----

-----

-----

-----

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.19

from which this Corner bears

S 74. E

side of


Tree

tree 8 inches diameter, on the

East

Metal Location Poster is on a n

Aspen



(Make sketch of topography near Corner)

T. 198 N. R. 29 W. S. 34 P. Mer.

V-1