

U. S. Department of Agriculture

FOREST SERVICE

V5

Chippewa..... NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 29 W. 5th. P. Mer.

Section..... Corner common to Sections

30, 31, 29, and 32

Corner consists of a Wood Post (stone) in place


State condition Good

Dimensions above ground 40 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of..... is located.....

Pits are located.....

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig. B. Ts.



Mkd.

S 30

New B. Ts.

S 29



Species Aspen Aspen Aspen Aspen

Diameter 16" 5" 6" 10"

Bearing N. 38° E. S. 44° E. N. 44° W. N. 44° E.

Distance 13 19 15 11

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?.....

John A. Gjelhaug

(Signature)

11/27/39

(Date)

Jr. Civil Eng.

(Title)

Dotted lines for writing notes.

Corner again.

Give any further facts which will aid in finding this


0.21 chains distant.

from which this Corner bears S. 72° W.

side of Tree

tree 8 inches diameter, on the S.W.

Metal Location Poster is on an Aspen



(Make sketch of topography near Corner)

T. 148 N., R. 29 W., 5th. P. Mer.