

U. S. Department of Agriculture
FOREST SERVICE

F9

Chippewa..... NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 29 W. 5th. P. Mer.

N. Sixteenth..... Corner common to Sections

.....,, 8....., and 9.....

Corner consists of a **Scribed Post** ~~post~~ in placeState condition **Good**.....Dimensions above ground **30**..... inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION**DIAGONAL POSITION**

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

County	B. Ts.
N 1/16	N 1/16
S 9	S 9

--

--

B. T.	B. T.

--

--

Species **Aspen**..... **Aspen**.....Diameter **6"**..... **5"**.....Bearing **N42° E.**..... **S. 74° E.**.....Distance **17**..... **16**.....Do you believe this to be a genuine Land Office Corner? **No**If not, why? **County corner Established by****County Surveyor.**.....**H. Hoard**.....

(Signature)

11/16/39.....

(Date)

Compass Man.....

(Title)

