

U. S. Department of Agriculture
FOREST SERVICE

J13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 29 W. 5th. P. Mer.



Section _____ Corner common to Sections
9, 10, 15, and 16

Corner consists of a Wood Post ~~post~~ in place
State condition Good

Dimensions above ground 36 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig. B.Ts. S 10	B.Ts. S 16		
B.T.	B.T.		

Species J. Pine J. Pine

Diameter 22" 18"

Bearing N. 60° E. S. 51° W.

Distance 31 $\frac{1}{2}$ 31

Do you believe this to be a genuine Land Office Corner? **Yes**

If not, why? _____

H. Hoard

(Signature)

11/17/39

(Date)

Compass Man.

(Title)

Corner again.

Give any further facts which will aid in finding this


0.51 chains distant

from which this Corner bears N. 51° E.

side of Tree

18 inches diameter, on the N.E.

Metal Location Poster is on a J. Pine



(Make sketch of topography near Corner)

T. 148 N. R. 29 W. 5th. P. Mer.