

U. S. Department of Agriculture
FOREST SERVICE

G 13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 29 W. 5th. P. Mer.

Quarter Corner common to Sections

, 9, and 10

Corner consists of an Aspen Post ~~rock~~ in place

State condition Good

Dimensions above ground 40 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

	•	•	
--	---	---	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

County
$\frac{1}{4}$
S 10

B. Ts.
$\frac{1}{4}$
S 9

--

--

B. T.

B. T.

--

--

Species Elm Oak

Diameter 10" 12"

Bearing N. 73° E. S. 67° W.

Distance 43 42

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

H. Hoard

(Signature)


11/16/39

(Date)

Compass Man

(Title)

Metal Location Poster is on an Oak tree 12 inches diameter, on the N.E. side of Tree from which this Corner bears N. 67° E. 0.42 chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 148 N. R. 29 W. 5th P. Mer.